


CLEANING WORKS REPORT

PROJECT No: #####

FLOUR SILO A01 INTERNAL CLEANING
XYZ BAKERS – LONDON

0800 888 6638 | www.rappel.ltd.uk | sales@rappel.ltd.uk

Rappel
↓ ↓



SILO CLEANING REPORT

PROJECT No: #####



Flour Silo A01 Internal Cleaning XYZ Bakers – London

ISSUE: 1.0



> Project Location & Client Details

Site Address	XYZ Bakers Baker Street London AB1 2CD	Grid or Lat/Lng Ref	53.424811, -2.516667
		Plant / Asset ID	Flour Silo A01
		Client	XYZ Bakers
		Client Representative	John Smith
		Client Contact No	020 1234 5678

> Document Control

Prepared By:	Stu Lightford	Approved By:	Nick Adamson
Date:	24/08/2015	Date:	24/08/2015
Signature:		Signature:	

SILO CLEANING REPORT

PROJECT No: #####



1. Asset / Plant Details

Asset / Plant Type:	Product Storage Silo
Asset / Plant ID:	Flour Silo A01
Description:	The silo is used for the storage of flour product and is located externally at the site. Approx. 30t capacity / 20m height / 3m diameter – aluminium shell construction.
Access:	Ladder access and protected gantry to the top of the silo. Access hatch located in the roof plate. Rope access system used for access / egress.

2. Cleaning Works

Cleaning Scope:	Dry clean of the internal silo surfaces to remove accumulated deposits. Visual inspection carried out.
Date of Clean:	24/08/2015
Next Clean Due Before:	24/08/2016
Comments / Recommendations:	<p>Cleaning works complete, filter units changed. The silo structure has been well maintained and was noted to be in a good condition at the time of cleaning with no defects evident.</p> <p>All external cladding, explosion vents, ladder access and services appear in good condition with no defects noted.</p>

We'll send you a reminder when your next clean is due

SILO CLEANING REPORT

PROJECT No: #####



3. Pre-clean Photographs 01-02

Photo No: 01 Pre-Clean: View showing accumulated deposits to the internal wall surfaces.



Photo No: 02 Pre-Clean: View showing accumulated deposits to the internal wall surfaces.



SILO CLEANING REPORT

PROJECT No: #####



3. Pre-clean Photographs 03-04

Photo No: 03 Pre-Clean: View showing accumulated deposits to the internal wall / roof surfaces.



Photo No: 04 Pre-Clean: View showing pre-clean conditions.



SILO CLEANING REPORT

PROJECT No: #####



4. Post-clean photographs 01-02

Photo No: 01 Post-Clean: View showing the cleaning works being undertaken



Photo No: 02 Post-Clean: View showing the cleaning works being undertaken.



SILO CLEANING REPORT

PROJECT No: #####



4. Post-clean photographs 03-04

Photo No: 03 Post-Clean: View showing the silo walls after cleaning.



Photo No: 04 Post-Clean: View showing silo after cleaning.

